

AA100W MAJOR SERVICE KIT



No	PARTS LIST	SIZE	ITEM NO	EA
1	Ball Bearing	3206	GR-ED7-001	2
2	Ball Bearing	3205	GR-ED7-002	2
3	Ball Bearing	6006ZZ	GR-ED7-003	2
4	Ball Bearing	6005ZZ	GR-ED7-004	2
5	Lock Nut	05	GR-ED7-005	4
6	Lock Nut Washer	05	GR-ED7-006	4
7	Lock Nut	06	GR-ED7-007	4
8	Lock Nut Washer	06	GR-ED7-008	4
9	Center Shim-MP	32*25*0.1	GR-ED7-009	10
10	Center Shim-BP	37*30*0.05	GR-ED7-010	6
11	Shim	14*7*0.1	GR-ED7-011	20
12	O-Ring (VITON)	G240	GR-ED7-012	2
	O-Ring (VITON)	G210	GR-ED7-013	2
	O-Ring (VITON)	V100	GR-ED7-014	1
	O-Ring (VITON)	G170	GR-ED7-015	2
	O-Ring (VITON)	G160	GR-ED7-016	2
	O-Ring (VITON)	G75	GR-ED7-017	7
	O-Ring (VITON)	G65	GR-ED7-018	4
	O-Ring (VITON)	G55	GR-ED7-019	4
	O-Ring (VITON)	AS025	GR-ED7-020	4
	O-Ring (VITON)	AS024	GR-ED7-021	2
	O-Ring (VITON)	AS320	GR-ED7-022	2
	O-Ring (VITON)	AS022	GR-ED7-023	4
	O-Ring (VITON)	S25	GR-ED7-024	4
	O-Ring (VITON)	S28	GR-ED7-025	2
	O-Ring (VITON)	S30	GR-ED7-026	4
	O-Ring (VITON)	P16	GR-ED7-027	10